

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Eldhouse Paul  
Vimal Jyothi Public School  
Kadavoor (P.O), Kothangangam  
Separately Attached

5. Period for which the certificate is issued

2024 - 2025

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

} NIL

7. Any major defects noticed which will render the building unsafe in any manner

NIL

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on ..... 15-06-2024 and found to be fit / unfit to conduct classes, for the period ..... 2024 - 2025 for the reasons stated above.

Place : Paingottor  
Date : 15-06-2024

(Seal)

Assistant Engineer  
ASSISTANT ENGINEER  
L.S.G.D. Section  
Paingottor

500/8-6-13

